

**United States Environmental Protection Agency  
Criminal Investigation Division  
Investigative Activity Report**

**Case Number**

0700-0469

**Case Title:**

Jacam Chemicals LLC

**Reporting Office:**

Kansas City Area Office

**Subject of Report:**

Report of photo documentation of Injection well

**Activity Date:**

January 17, 2014

**Reporting Official and Date:**

(b) (6), (b) (7)(C)

Special Agent

21-JAN-2014, Signed by: (b) (6), (b) (7)

**Approving Official and Date:**

(b) (6), (b) (7)(C)

Special Agent in Charge

24-JAN-2014, Approved by: (b) (6), (b) (7)(C)  
Assistant Special Agent in Charge

**SYNOPSIS**

SA (b) (6), (b) (7)(C) obtained photographs of the tank battery, tire tracks going over the secondary containment berm and the injection well.

**DETAILS**

On January 17, 2014, SA (b) (6), (b) (7)(C) obtained photographs of the tank battery and injection well where a Jacam truck was observed the following evening (Jan 16, 2014.) The injection well is located east of the Jacam Chemicals Production facility on Avenue Q approximately 13.5 miles but prior to Plum Avenue just southeast of Lyons, Kansas.

The photographs indicate tank battery lease information, show tire tracks over the secondary containment berm and injection well.

See photographs for details

**ATTACHMENT**

InjectionWell1.JPG

InjectionWell2.JPG

InjectionWell3.JPG

InjectionWell4.JPG

InjectionWell5.JPG

InjectionWell6.JPG

InjectionWell7.JPG

This document contains neither recommendations nor conclusions of the EPA.

It is the property of the EPA and is loaned to your agency;  
it and its contents are not to be distributed outside your agency.